

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECTION I

MANUFACTURER'S NAME BRAY OIL COMPANY, INC.		EMERGENCY TELEPHONE NO. (714) 660-9414
ADDRESS (Number, Street, City, State and ZIP Code) 16815 Von Karman Ave., Suite 202, Irvine, CA 92714		
CHEMICAL NAME AND SYNONYMS Corrosion Preventive, Fingerprint Remover		TRADE NAME AND SYNONYMS Braycote 120
CHEMICAL FAMILY Petroleum	FORMULA Mil-C-1507L	

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS Aliphatic Hydrocarbon	21	500ppm	FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES	%	TLV (Units)
Methyl Amyl Alcohol, MG/M3	21	100

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	300	SPECIFIC GRAVITY (H ₂ O=1)	0.878
VAPOR PRESSURE (mm Hg.)	Not Determined	PERCENT VOLATILE BY VOLUME (%)	65
VAPOR DENSITY (AIR=1)	< 1	EVAPORATION RATE (ethyl ether=1)	< 1
SOLUBILITY IN WATER	Soluble		
APPEARANCE AND ODOR	Amber Liquid, characteristic solvent odor		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used) ASTM D56, TCC	102°F	FLAMMABLE LIMITS Not Determined	Lei	Uei
EXTINGUISHING MEDIA Dry Chemical, Carbon Dioxide, Foam or Water Fog				
SPECIAL FIRE FIGHTING PROCEDURES Do not use water except as fog to cool containers as tanks to avoid heating above flash point.				
UNUSUAL FIRE AND EXPLOSION HAZARDS				

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
Cited at 500 ppm in air.

EFFECTS OF OVEREXPOSURE

Drowsiness, headache, nausea, narcosis.

EMERGENCY AND FIRST AID PROCEDURES

Overexposure - move to fresh air. Skin Contact - wash with soap and water.

Contact with eyes - flush with water, contact physician.

Ingestion - do not induce vomiting, contact physician immediately.

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	

INCOMPATIBILITY (Materials to avoid)
Avoid strong oxidizing agents

HAZARDOUS DECOMPOSITION PRODUCTS
Products of combustion: CO, CO₂, SO₂, and smoke.

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Avoid sources of ignition. Ventilate room, wipe up with rags using gloves, or used slop oil disposal agent. Store in covered metal containers and dispose of as soon as possible.

WASTE DISPOSAL METHOD
Incineration or method in compliance with federal, state, and local regulations regarding health, air, and water pollution.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type)
If used in a closed area, use fresh air mask.

VENTILATION	LOCAL EXHAUST	SPECIAL
	MECHANICAL (General) Yes	OTHER

PROTECTIVE GLOVES Recommended - Buna N	EYE PROTECTION Splash Goggles
---	----------------------------------

OTHER PROTECTIVE EQUIPMENT
Avoid contact with skin.

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Normal precautions in handling petroleum products. Store in well ventilated area away from sources of heat or ignition.

OTHER PRECAUTIONS
Keep in closed metal containers.

PAGE (2)
GPO 930-543

Form OSHA-20
Rev. May 72

JE/bh
June 79

"The information presented herein has been compiled from sources considered to be dependable and is accurate to the best of seller's knowledge, however, seller makes no warranty whatsoever, expressed, implied, or of merchantability regarding the accuracy of such data or the results to be obtained from the use thereof. Seller assumes no responsibility for injury to buyer or to third persons or for any damage to any property and buyer assumes all such risks."